



2

3

4

2P+T	50/60	200-250		6	311.1643 (▲)(Δ)	311.3243	321.3243
	50/60	380-415		9	311.1648	311.3248	
	50/60	480-500		7			
	50/60	trasf.		12			
	>300-500	>50		2			
	c.c.	>50-250		3			
	c.c.	>250		8			
	50/60	100-130		4	311.1641	311.3241	
	50/60	200-250		9	311.1644	311.3244	
	50/60	380-415		6	311.1646	311.3246	321.1646 321.3246
3P+T	60	440-460		11			
	50/60	480-500		7			
	50/60	600-690		5			
	50/60	380-440		3			
	100-300	>50		10			
	>300-500	>50		2			
	50/60	100-130		4	311.1642	311.3242	
	50/60	208-250		9	311.1645	311.3245	
	50/60	346-415		6	311.1647	311.3247	321.1647 321.3247
	50/60	480-500		7			
3P+N+T	50/60	600-690		5			
	60	440-460		11			
	50/60	380-440		3			
	>300-500	>50		2			

Tensión nominal >50V

- Aprobaciones: de pág. 561



Bornes de tornillo



Bornes de perforación del aislante



Bornes de resorte

Más información de pág. 36



(▲) De color negro

Versiones también disponible en negro; solo agregar "K" al final de cada referencia. Ejemplo: 313.1643K

310.1643	310.3243	313.1643 (▲)(Δ)	313.3243 (▲)	313.1643H (▲)	313.1643P (▲)(Δ)	313.3243F (▲)
		313.1648	313.3248	313.1648H	313.1648P	313.3248F
		313.16436	313.32436			
		313.16433	313.32433			
		313.16432	313.32432			
		313.16434	313.32434			
		313.16438	313.32438			
		313.1641	313.3241			
310.1644	310.3244	313.1644	313.3244	313.1644H	313.1644P	313.3244F
310.1646	310.3246	313.1646 (▲)	313.3246 (▲)	313.1646H (▲)	313.1646P (▲)	313.3246F (▲)
		313.16465	313.32465			
		313.16466	313.32466			
		313.16467	313.32467			
		313.16464	313.32464			
		313.16461	313.32461			
		313.16462	313.32462			
		313.1642	313.3242			
		313.1645	313.3245			
310.1647	310.3247	313.1647 (▲)	313.3247 (▲)	313.1647H (▲)	313.1647P (▲)	313.3247F (▲)
		313.16476	313.32476			
		313.16477	313.32477			
		313.16475	313.32475			
		313.16474	313.32474			
		313.16472	313.32472			



(Δ) Mango transparente

Versiones también disponible en transparente; solo agregar "TP" al final de cada referencia. Ejemplo 311.1643TP.